and the second s	Approved For Release		IA-RDP80-00810A	002300110006	
COUNTRY <u>East Ge</u>	CLASSIFICATION SECTIONARY	S.CURITY IN	FORMATIONREPORT NO.		25X1A
OPIC Brandis	Airfield	and the second of the second s	n dit distince sinc de reprimerant de 1923 o 1920 des de 1920 d	trackers and positive attraction products and an inches or	
- 300 transport, 11-page 200-st opportunities (Securitaria) and an every employee and execution	minerang novembers until graph articularly a mandrate garbon distribute description and control of the control				engatikennumovamideres abt da 12 metapostana
VALUATION Bed	e below PLACI	E OBTAINED		25X1C	derland one, we construit ready ready ready to the control of the
DATE OF CONTENT.	3 June to 19 July 1953	- The state of the	namenaker sincan örröliyö rörriler samran ar sasan sakaran sakar	randa an rangado estre aprila a como esta esta de la como de esta de la como de esta de la como de esta de la c	
ASTE 10BTAINED			PARED 13 Aug	ruet 1053	ting dankantin kannya tika arawa 1960 terdikutikan di kapinya yan a
	_ENCLOSURES (NO. & TYPE		tches on ditto		Name kale makeriman kale di aparta para ang panggangan panggangan panggangan panggangan panggangan panggangan
		gree .	<u>, </u>		•
Colo. Antiferioria. A res. All black and Australian and Australia (Australia) (Australia) (Australia) (Australia)		z ser i i i i	ě		THE CONTRACT
· · · · · · · · · · · · · · · · · · ·	Lik saarbinaan voorgevoor on maa semas van	· Marie and			-turin (± 1844,500 cm risisty o y n upry)bra in <u>me</u>qaso (<u>1</u> 62 ° <u>1679)</u>
25X1X	- - -	100	A STATE OF THE PARTY OF THE PAR	ik de lide r ik vener da ik k er 10 rayu dia 12 ilayina er engek <u>arana re</u>	«ССУ» III Монтонава на основни помента на примеро на однова на
OTHER RESIDENCE AND ASSESSMENT OF THE PROPERTY			25	X1X	
 25X1X				7.	
ann 3 to	following air activity 1 July 1953: 2 7 June. Some flights erved aloft. The weather	. Were made h	or Poza On 5 To		
<u>8 Ju</u> ever	me. There was no air ning at 7 p.m. After ni erved aloft.	activity thr	oughout the day	. Flying bega	an in the
9 J	me. Flying was practi	cod between	9 .m. and midn	lgh t.	
10 Jabou	une. There was no air	activity ex	cept for the tal	te-off of a l	'o-2 at
17.	nd 18 June, No flight	s were condu	cted.		
	une. Nine Li-2s laded rnoon. A total of abouing.	at 2:45 p.: t 36 Li-2s we	a. and other pla ere parked at th	nes landed i e field in t	n the he
<u>20 J</u> The	une. Between 6 a,m. a weather was cloudless.	nd 2 p.m., . f	ground attack pl	anes practic	ed flying.
<u>21 a</u>	nd 22 June. There was	no air activ	vity by ground a	ttack planes	a
23 J star	une. No flights were reted at about 7 p.m.	made throughous	out the day. Nig	ht flying by	I1-10s
25 June which	ne. Il-10s were obser time the degree of cl	ved aloft be oudiness cha	tween 7 a.m. an	d 4 p.m., du	ring
<u>26 ar</u> and 1	nd <u>27 June.</u> No air act rain.	ivity was co	nducted. There i	vas a closed	ceiling
28 Ju Weire	me. At about 5:30 p. m observed aloft.		ne planes with o	eargo gliders	
	CLASSIFICATION SECR	Dale			

... 2 ...

SECRET

25X1A

25X1

30 June. At about 8 a.m., 26 Li-2s took off heading west. There were no clouds, at 8:30 a.m., take-offs were made by six twin-engine planes towing cargo gliders. The Li-2s returned to the field at about II a.m. Twin-engine planes towing cargo gliders took off at 11:30 a.m.

Liuly, After 7 para, low level attacks were made. After nightfall, night flying was conducted by Il-1's.

 $2 \ July$. After 8 a.m., landings were made by Li-2s and twin-engine planes towing cargo gliders. The ground attack planes again practiced night flying after 7 b.m.

3 July Between 7 a.m. and 3 p.m., Il-10s practiced flying individually and in formations.

A and 5 July. There was air activity by Li-2s and also by twin-engine clanes towing cargo gliders which headed west and returned from the same direction.

6 July. I1-10s flew individually and in formation between 5 p.m. and 2 a.m.

7 July. Twenty-five Li-2s landed at 8:15 a.m. and 9 Li-2s at 3:30 a.m.

8 July. Ground attack planes practiced formation flying during the daytime.

9 July. A L1-2 took off at 4:45 a.m. and a formation of 24 L1-2s took off at 5:55 a.m. Additional take-offs and landings were made by L1-2s during the early morning. Between 10 a.m. and 5 p.m., ground attack planes practiced flying.

10 July. Between 11 a.m. and noon and at about 4 p.m., take-offs and landings were made by ground attack planes.

11 July L1-25 flying in formations took off after 6 a.m. and landed after 5:35 a.m.

12 July. There was no air activity and the weather was partly cloudy. In the afternoon, 27 twin-engine planes were counted at the field.

11 July. Ground attack planes were observed aloft around noon and again after 6:30 p.m.

14 July. A few Il-10s practiced flying. 1

3. Every day between 10 and 19 July, IL-10s made individual and formation flights and practiced diving. On 19 July, 32 IL-10s, 2 Po-2s and 1 Yak-14

SECRET/

25X1X

Suggest.

25X1/	Δ
-------	---

. 3 **


were carried at the field. On the morning of 15 July, approximately 35 Li-2s and 6 carry gliders departed from the field and headed east.


- The cargo gliders which were observe at the field in June and July 1953 were protebly of all-wood construction and were painted green. The only parking or them was a red star on the stabilizing surface of the rudder and unbig. The losslage appeared rectangular when viewed from the front. The nose was shaped life, a quadrilateral operand with convex sides. The rear section of the fuselage was curved upward and the elevator assembly had a vertical rear edge which was it and higher than the sings. The wings had shight positive dihedral, with each having , one wing strut connected to the fuscisge. The leading edges of two wings were straight as far as the middle and them slightly curved to the rear. The wing the were rounded off. The landing goar was fitted approximately in the middle of the wing and under the wing strut, with the wheels at both sides of the firselage. When compared with the towing plane of I1-12 type, the cargo glider appeared to be slightly smaller with a slightly plumper fuselage and a slightly smaller wing span but about the same length of fuselago. 3 The cargo glidars were trucked to the take-off point and there attached to the towing plane of type II-12. The towing plane probably had its towing device in an aperture at the rounded-off and of its fuselage. The towing rope was approximately 80 me-Their rudder and elsewtor assemblles were painted yellow. The II-I2s towing the cargo glip 25X1 ters in length. ders took off individually, backed one time and, then, circled over the field assembling in formations of threes. The individual formations flaw one behind each other. The Li-2s as well as the It-12s towing the cargo gliders glways beeded west and returned from the same direction. When returning to the field with a westerly wind, the planes flew along the southern edge of the landing Tiold. The cargo glider towed by the leading clane was released about in line with the center of thelanding field and the other cargo gliders, successively. Rolfoved at intervals of about 100 meters. Subsequently, the released gliders ands an abost seep banked turn before landing south of the runway at intervals of about 50 peters. They came to a stop near the center of the landing Rield and were then trucked away. Although no Loading operations were observed, source inferred from the careful handling of the cargo gliders at the take-off and during the subsequent flight that they were probably loaded with cargo at the field. They apparently returned empty, as the landings were made light and smooth. Source could not observe whether the Li-2s or fi-12s were loaded, 4 The Li-2s and Hi-12s with cargo gliders which had together excived of the field were marked in the name dispersal area and were observed flying together. Source could not determine whether they were assigned to one whit of 25X1 chether they formed one unit only during their assignment at Brandic sirfield.
- is The ground attack planes racticed flying independent of the transport unit, Their status of formation flying had apprently improved. Source determined that the IL-10s had steeper dives than previously and that they repeatedly have led off just above the ground.
- i. <u>Field Compant.</u> Brandis sinfield is occupied by a ground attack regiment which is equipped with II-10s and some Po-2s. Between 19 June and 15 July 1953, a transport which with about 35 Li-2s and some II-12s, with one cargo whider each, was also stationed at the field. This unit probably came from outside Cast Germany. It held air transport and air landing expresses during the period under review. The planes landed at Friunt-Bindersleben airfield.

AFORETY


Annex 1

Cargo Glider Observed at Brandis Airfield





Seen from below



Approved For Release 2002/07/22:	

STORET

Ā	lnnex	2

25X1A

Marking Observed on Li-2 Plane at Brandis Airfield